

PUBLIC WORKS DEPARTMENT.

No. S. 12.—It is hereby notified that sealed tenders in triplicate, which should be clearly marked "Tender for Metalling and Tar-painting the hilly portions of Lai Chi Kok, Castle Peak and Taipo Roads", will be received at the Colonial Secretary's Office until Noon of Monday, the 26th day of January, 1925, for Metalling and Tar-painting the hilly portions of Lai Chi Kok, Castle Peak and Taipo Roads.

No work will be permitted on Sundays.

For form of tender, specification and further particulars apply at this Office.

The Government does not bind itself to accept the lowest or any tender.

HAROLD T. CREASY,
Director of Public Works.

9th January, 1925.

No. S. 13.

NOTICES TO MARINERS.

Shipping is warned to use the utmost caution when navigating through the South Channel of the Hainan Straits. S.S. *Wing Hong* reports having grounded in a position $1\frac{1}{2}$ to 2 cables N. 40° W. from the Red Buoy and on the line of Riversdale Buoy and the small Hill marked 89 ft. on Admiralty Chart No. 876.

G. F. HOLE, Lieut.-Comdr., R.N.,
Harbour Master, &c.

HARBOUR MASTER'S DEPARTMENT,
HONGKONG, 2nd January, 1925.

The Government of the Philippine Islands
Department of Commerce and Communications
BUREAU OF COMMERCE AND INDUSTRY
MANILA

December 24, 1924.

No. 685.

**Cebu—East Coast—Northern Entrance to Cebu Harbour—
New Position of Buoy.**

The second class black can buoy No. 1 at the point of reef N.E. of Bentolinao Point, northern entrance to Cebu Harbor, has been moved northward. The buoy is now moored in 47 feet of water.

Sextant angles as follows:—

Right angle Pangtian Point to Bagacay Point Lighthouse ...	78° 50'
Left angle Bagacay Point Lighthouse to Point northeastern coast to entrance of Cansaga Bay ...	100° 10'

See No. 127, List of Buoy, etc., 1924.

Calamian Group—Coron Passage—Boy Missing.

The third class red nun buoy in Coron Passage, Calamian Group, has been reported missing. It will be replaced to its former position as soon as practicable and proper notice will then be issued. See No. 176, List of Buoys, etc., 1924.

**Luzon—South Coast—San Bernardino Strait—Calantas Rock
Light not Burning.**

The automatic acetylene flashing white light on Calantas Rock western entrance of San Bernardino Strait, has been reported not burning. It will be relighted as soon as practicable and proper notice will then be issued. See No. 61, List of Lights, etc., 1924.

FIDEL A. REYES,
Director.

PUBLIC WORKS DEPARTMENT.

No. S. 432.—It is hereby notified that the following Sale of Crown Land by Public Auction will be held at the Offices of the Public Works Department on Monday, the 12th day of January, 1925, at 3 p.m.

Full Particulars and Conditions may be obtained at this Office.

PARTICULARS OF THE LOT.

No. of Sale.	Registry No.	Locality.	Boundary Measurements.				Contents in sq. feet.	Annual Rental.	Upset Price.
			N.	S.	E.	W.			
1	Kowloon Inland Lot No. 1946.	Adjoining Kowloon Inland Lot No. 1457, Kau Pui Shek.	feet.	feet.	feet.	feet.	1,860	\$ 12	\$ 2,790
			As per sale plan.						

The Purchaser of the Lot will also have to pay the sum of \$25 for boundary stones required to define the Lot and \$30 for the Crown Lease.

HAROLD T. CREASY,
Director of Public Works.

24th December, 1924.

PUBLIC WORKS DEPARTMENT.

No. S. 433.—It is hereby notified that the following Sale of Crown Land by Public Auction will be held at the Offices of the Public Works Department on Monday, the 12th day of January, 1925, at 3 p.m.

Full Particulars and Conditions may be obtained at this Office.