

No. S. 287.

NOTICES TO MARINERS.

Position given for Tathong Point Light, Lam Tong in Notice to Mariners No. S. 431, published in the Government Gazette of 2nd December, 1921, is incorrect and should read:—

Latitude 22° 14' 23" N.
Longitude 114° 17' 12" E.

G. F. HOLE,
Harbour Master, &c.

HONG KONG, *13th October, 1926.*

The Government of the Philippine Islands
Department of Commerce and Communications
BUREAU OF COMMERCE AND INDUSTRY
MANILA

August 19, 1926.

No. 711.

Cebu—Northern Entrance—Buoy Adrift.

The second class red nun buoy No. 8, off Mandaue tower has been reported adrift. It will be replaced to its former location as soon as practicable and proper notice will then be issued. See No. 127, List of Buoys, etc., 1926.

**Cantanduanes Island—Western Extremity—Sialat Point—
Light Re-established.**

The 6th Order Occulting white light on western extremity of Catanduanes Island which was reported as not functioning in Notice to Mariners No. 709, dated August 5, 1926, has been re-established. See No. 69, List of Lights, etc., 1926.

October 5, 1926.

No. 713.

Balabac Island—Balabac Light—Characteristic Restored.

The occulting white light on Espina Point, south side of entrance to Balabac Harbor which was reported as fixed white in Notice to Mariners No. 708, dated July 16, 1926, has been restored to its normal condition. See No. 155, List of Lights, etc., 1926.

FIDEL A. REYES,
Director.