NOTICES TO MARINERS.

Notice is hereby given that a junk has sunk in the track of steamers in eight fathoms of water between Koh Lak and Koh Takut, some miles north of Koh Lak, showing two of her masts 4-5 feet above water.

The approximate position is N. Lat. 11° 55′ and E. Long. 99° 52′ 5″.

By Order of H. E. the Minister of Local Government.

PHYA VISUTRE SAGORADITH.

Harbour Master General.

BANGKOK, 22nd August, 1919.

SPECIAL NOTICE TO MARINERS, No. 539.

CHINA SEA.

Yangtze River—South Channel Entrance.

Middle Ground Upper Buoy Damaged by Collision.

Notice is hereby given that the Middle Ground Upper Buoy, gas lighted, has been damaged by collision and will be replaced as soon as circumstances permit.

T. J. ELDRIDGE, Coast Inspector.

Coast Inspector's Office, Shanghai, 30th August, 1919.

SPECIAL NOTICE TO MARINERS, No. 540.

CHINA SEA.

SHANGHAI DISTRICT.

Yangtze River Approaches.

Ariadne Rock Whistling Buoy out of position.

Notice is hereby given that the Ariadne Rock Whistling Buoy is reported to have been driven about 2 miles to the south-westward of its advertised position. The Buoy will be replaced in position as soon as weather conditions permit.

T. J. ELDRIDGE, Coast Inspector.

COAST INSPECTOR'S OFFICE, SHANGHAI, 1st September, 1919.

PUBLIC WORKS DEPARTMENT.

No. S. 222.—The following description and terms of the proposed leases of certain Crown Lands at North Point, comprising portions of the Foreshore and Sea Bed, are published under the provisions of the Foreshores and Sea Bed Ordinance, 1901.

DESCRIPTION OF THE LOTS PROPOSED TO BE LEASED.

As shewn on plan signed by the Director of Public Works, which can be seen at the Office of the Public Works Department.