

PUBLIC WORKS DEPARTMENT.

No. S. 343.—It is hereby notified that sealed tenders in triplicate which should be clearly marked "Tender for Formation of Site, Laying Foundations and Building Retaining Walls for Bonham Road School", will be received at the Colonial Secretary's Office until Noon of Monday, the 13th day of November, 1922. The work consists of levelling the site to required levels, building retaining walls, and laying all foundations for a school to be built on the site adjoining Bonham Road and Western Street.

No work will be permitted on Sundays.

For Form of tender, specification and further particulars apply at this Office.

The Government does not bind itself to accept the lowest or any tender.

No. S. 344.—It is hereby notified that sealed tenders in triplicate, which should be clearly marked "Tender for Kowloon Hospital", will be received at the Colonial Secretary's Office until Noon of Monday, the 4th day of December, 1922. The work consists of the construction of five blocks of buildings together with offices and out-houses, etc., at Tai Shek Ku.

No work will be permitted on Sundays.

For Form of tender, specification and further particulars apply at this Office.

The Government does not bind itself to accept the lowest or any tender.

T. L. PERKINS,
Director of Public Works.

20th October, 1922.

No. S. 345.

NOTICES TO MARINERS.

The Government of the Philippine Islands
Department of Commerce and Communications
BUREAU OF COMMERCE AND INDUSTRY
MANILA

October 10, 1922.

No. 637.

Cebu—Cebu Harbor—Northern Entrance—New Position of Buoy.

The second class red nun buoy No. 10 on Banitac Shoal has been moved about 120 meters southward to mark the edge of the outer shoal. Moored in 3-1/2 fathoms of water, coral bottom. Bearing: round tower Mandane bears N. 56° E.; distance, 1-1/4 miles. See No. 128, List of Buoys, etc., 1922.

Mindanao—North Coast—Kolambugan—Range Rebuilt.

The rear beacon of the Kolambugan range which was reported collapsed in Notice to Mariners No. 628, dated May 24, 1922, has been rebuilt, and the light functioning. See No. 155, List of Lights, etc., 1922.