GOVERNMENT NOTIFICATION.—No. 440.

The following Hydrographic Notices are published for general information.

By Command,

A. LISTER, Acting Colonial Secretary

Ary's Office, Hongkong, 26th October, 1889.

Government of China.

NOTICE TO MARINERS.

No. 231.

CHINA SEA.

Mariners has been received from the Acting Commissioner of Customs at Jenchuan, Corea: COREA.

NOTICE TO MARINERS,

No. 2.

JENCHUAN DISTRICT.

Tidal Beacon on Observation Island.

NOTICE is hereby given that a stone Tidal Beacon has been erected on the south-eastern point of Observation Island, in

The Beacon is the steel with red and white horizontal bands, each three feet broad.

When the water three steel of one of these bands, the figure painted on such a band indicates the least depth of water, in feature be found in the channel across the bar to the Inner Harbour.

By Order of the Chief Commissioner of Customs,

J. F. SCHŒNICKE, (Signed) Acting Commissioner of Customs.

CUSTOM HOUSE, JENCHUAN, 30th September 1889.

By Order of the Inspector General of Customs,

E. V. BRENAN, Acting Coast Inspector.

IMPERIAL MARITIMS COSTOMS, COAST INSPECTOR'S OFFICE, SHAREHAL, 10th October 1889.

Government of South Australia.

NOTICE TO MARINERS.

No. 2 of 1889.

PORT DARWIN.

BUOYS AND BEACONS.

Notice is here given that the following Buoys and Beacons have been provided at Port Darwin:—
Two Mooring govs have been placed near the Palmerston Jetty. The one to the eastward is moored in 30 feet water at L.W.S., 590 feet on the outer end of the jetty, and 300 feet from the nearest part of the bank.

The one to the stward is moored on the edge of the mud flat, in 2 feet water at L.W.S., and is 530 feet from the

outer end of the jeff.

An Iron Beacon with a Can Top has been placed on the outer edge of the mud flat extending from Middle Point. The An Iron Beacon with a Can Top has been placed on the outer edge of the mud flat extending from Middle Point. The Hill on Middle Point bears from the Beacon S. 22° E. Vessels should not approach the Beacon within one and a half (1½) cables at L.W.S.

Two Beacon with a Can Top has been placed on the outer edge of the mud flat beacon within one and a half (1½) cables at L.W.S.

Two Beacon with a Can Top has been placed on the outer edge of the mud flat to the edge of Jervois-road, immediately under the Government Residence, and the other on the mud flat to the westward of Fort Hill. The Beacons bear N.E. and S. Trom each other.

Masters of value are hereby cautioned not to anchor close inshore until the inner Beacon is open to the eastward of

From the outer Beacon the Cable trends to W.N.W.

THOS. N. STEPHENS. Secretary Marine Board.

Marine Board Port Adelaide, 6th September, 1889.