- (13) The transforming apparatus at any sub-station supplied at extra high pressure shall be so arranged that there shall be no danger of any mains connected therewith being charged to any pressure beyond the limits of pressure for which those mains are intended.
- (14) In delivering the energy to a sub-station at extra high pressure the company shall exercise all due precautions so as to avoid risk of causing fire on the premises.
- (15) All extra high pressure electric lines and apparatus placed in a sub-station shall be highly insulated and thoroughly protected against injury to the insulation or access of moisture, and any metal forming part of the electric circuit shall not, unless efficiently connected with earth, be exposed so that it can be inadvertently touched. All such lines shall be so fixed and protected as to prevent the possibility of electrical discharge to any adjacent metallic substance.
- (16) The Director of Public Works shall be entitled to enter at all times any of the generating or sub-stations of the company supplying or supplied at an extra high pressure, and to make any such examination and tests of the mains, machines, transformers, or other apparatus in use in those stations, as may appear to him necessary, and the company shall afford all due facilities for any such examination and tests.
- (17) Where any extra high pressure circuit is connected with earth, the connection shall be made at one point only, namely, at the generating station, sub-station, or transformer, and the insulation of the circuit shall, except at that point, be efficiently maintained throughout.
- (18) The neutral point of the star winding of each distinct three-phase circuit, used for extra high pressure, may be connected with earth, or may be insulated. If connected with earth through a resistance, that resistance shall be sufficiently low to ensure that the fuse or automatic circuit-breaker in the mains shall act.

If the neutral point is not connected with earth, a separate electrostatic voltmeter placed in a conspicuous position in the generating station shall be connected between each distinct circuit and earth; and if the indications of the voltmeters show that the insulation of any of the circuits is faulty, immediate steps shall be taken to restore the insulation.

## Penalties.

Penalties for default. 40. If the company make default in complying with any of the preceding regulations, they shall, on summary conviction, be liable to a penalty not exceeding 100 dollars for every such default, and in the case of a continuing offence to a further penalty not exceeding 100 dollars for each day during which the offence continues.

The recovery of a penalty under these regulations shall not affect the liability of the company to make compensation in respect of any damage or injury which may be caused by reason of the default.

2. The regulations made by the Governor in Council on the 2nd April, 1914, and the 22nd October, 1914, and published in the Gazette on the 17th April, 1914, and on the 13th and 20th November, 1914, respectively, are hereby rescinded.

S. B. B. McElderry, Clerk of Councils.

Council Chamber, 1st December, 1921.

## APPOINTMENTS, &c.

No. 503.—In accordance with the Full Court Ordinances, 1912 and 1915, His Excellency the Governor has, with the consent of the Principal Secretary of State for Foreign Affairs, been pleased to appoint His Honour Skinner Turner, Esquire, a Judge of His Britannic Majesty's Supreme Court for China, to be a Member of the Full Court of Hongkong.

29th November, 1921.